

WV100030

EN



Fire-resistant, scratch-resistant, and anti-fog polycarbonate eye protection. Requires Easy Click Adapters FR. Can be worn with corrective glasses. Compatible with all Quantum helmets. Meets EN 14458 Standard.

The ZEN PLUS VISOR mounted on the QUANTUM helmet, via the EASY CLICK ADAPTERS FR, makes the helmet usable for use in wildland firefighting (EN16471) and technical rescue activities (EN16473) where there is potential exposure to flames.

TECHNICAL DETAILS



MATERIAL
Polycarbonate



STANDARD
EN 14458



TEMPERATURE OF USE
-30°C / +50°C

EN 166
EN 170 (clear)
EN 172 (smoke, mirror)



OPTICAL CLASS
1

ANSI Z87.1



WEIGHT
80 g



CATEGORY
II

TECHNOLOGIES



ANTI-FOG

Equipped with an anti-fog treatment to increase wearer visibility when active and in a variety of conditions.



DRIP PROOF UPPER CONTOUR

Designed with a rubber upper contour to keep out sweat moisture and to enhance comfort.



CUT PROOF EDGE

Designed with a cut proof edge for enhanced comfort and safety.



PANORAMIC LENS

Wide view lens for optimal protection and visibility.



SCRATCH RESISTANT

Equipped with a scratch-resistant treatment for increased durability.



COMPATIBLE WITH GLASSES

Designed for use over corrective glasses.



EASY CLICK ADAPTERS FR

Fire-resistant and designed to easily attach and remove KASK eye and face protection accessories. Compatible with all Quantum helmets.

MARKINGS

CODE	COLOR	MARKINGS
WV100030-500	CLEAR	EN14458:2018 KASK ZEN PLUS 10/2022 = ⊙ BTKN 2C-1,2 -30°C+50°C E1/E3 CE 2754 UKCA 2C-1,2 KASK EN166 1BTKN / ANSI Z87+ U6 X D3
WV100030-510	SMOKE	EN14458:2018 KASK ZEN PLUS 10/2022 = ⊙ BTKN 5-1,4 -30°C+50°C E1/E3 CE 2754 UKCA 5-1,4 KASK EN166 1BTKN / ANSI Z87+ U6 L1.5 X D3
WV100030-520	SILVER MIRROR	EN14458:2018 KASK ZEN PLUS 10/2022 = ⊙ BTKN 5-2,5 -30°C+50°C E1/E3 CE 2754 UKCA 5-2,5 KASK EN166 1BTKN / ANSI Z87+ U6 L2.5 X D3

ADDITIONAL INFORMATION

GUARANTEE

3 years from date of purchase

SHELF LIFE

10 years starting from the date of manufacture. Shelf life depends on various factors that can cause deterioration such as sudden temperature changes, the amount of exposure to direct sunlight and the intensity of use. Altered vision and scratches are elements that signal the need to check for deterioration of the visor.

CLEANING

Clean only with water and mild soap. Allow to air dry. Do not use chemical detergents, solvents, petrol powders as they are too aggressive and could lower the structural resistance of the visor. Do not rub the lens when dry.

ZEN PLUS VISOR COLLECTION



WV100030-500
CLEAR



WV100030-500
SMOKE



WV100030-500
SILVER MIRROR



WAC00074
EASY CLICK
ADAPTERS FR

DISCOVER MORE



SCAN FOR
COMPLETE
COLLECTION